



INCORRECT LABEL ON DISTRIBUTION SERIES 2 ALARM SENSOR INPUT CONTACTS

DATE OF ISSUE: July 21, 2014

MODELS AFFECTED

- ICT180S-12I
- ICT180S-12IRC
- ICT180S-12B
- ICT180S-12BRC
- ICT180S-12BRCP

(On units shipped prior to July 18, 2014.)


OVERVIEW

This document is intended to highlight an error that appears on the rear-panel labeling for the Distribution Series 2 DC distribution panels.

The ALARM SENSOR INPUTS – shown on Figure 1 – are incorrectly labeled. These inputs are used to monitor external dry contact sensors used to provide alarm notifications for third-party devices such as door, smoke, heat and water sensors.


This incorrect labeling may cause these alarm notifications to function incorrectly, but only in situations where a user ties all input commons (“C”) together.

Figure 1 - Location of Alarm Sensor Inputs on rear panel



The correct labeling is shown in Figure 2.

Figure 2 - Correct label



REPLACEMENT LABELS

ICT will provide, at no cost, replacement labels that can be affixed over the existing label. To obtain, call 604-856-6303 or email sales@ictcorporate.com.